

# Under The Deck: LV 50




Figure 1

## LV 50 Stern Tanks 8<sup>th</sup> September 2017

Is there a 4<sup>th</sup> tank missing?




Figure 2

## LV 50 Starboard Front Stern Tank 8<sup>th</sup> September 2017




Figure 3

LV 50 Stern Tanks 8<sup>th</sup> September 2017

Badly rusted iron  
tanks, riveted  
construction

Figure 4

LV 50 Stern Tanks 8<sup>th</sup> September 2017

Pipe from  
forward tanks

Tanks conform to  
hull shape

Figure 5

# LV 50 Stern Tanks 8<sup>th</sup> September 2017

Plastic tank where  
4<sup>th</sup> tank might  
have been?

3<sup>rd</sup> tank behind  
port tank

Figure 6

LV 50 Stern Tanks 8<sup>th</sup> September 2017



Figure 7

# Under The Deck: LV 50 8<sup>th</sup> September 2017




Figure 8

## LV 50 Forward Tanks 8<sup>th</sup> September 2017




Figure 9

LV 50 Forward Tanks 8<sup>th</sup> September 2017



Welded iron tanks  
in better condition  
than Aft ones

Figure 10